## **CONTRACTORS GENERAL REMARKS**

## Work in progress

- i. Site Clearance has completed to 100%
- ii. Setting out has completed to 100%
- iii. Excavation has completed to 80%
- iv. Steel fixing in foundation, column and lift shaft has completed 100%
- v. Concreting on foundation and lift shaft has completed 100%
- vi. Concreting under floor column has completed 100%
- vii. Blinding, steel fixing and concreting in strip foundation has completed 60%
- viii. Under floor block wall has completed 40%

